



How to modify WS-PoE-Tester for 802.3af mode B and uPoE



Solder a jumper to bypass Q6

Mode B jumper as shipped



Remove jumper

